

From: STSCIC::FITCH 19-DEC-1991 09:45:10.19  
To: BIELEFELD,FSW1::STNGTF512,BALZANO,CHANCE,HARTIG,KINNEY  
CC: SCHWEIHS,FITCH  
Subj: Change to GIMP items in SHP

At yesterdays Flight Software Operations Working Group meeting, we discussed the GIMP flags in the SHP and it was determined that the job of zeroing out the GIMP Error Flag would now go to Vicki's group. Further discussion centered on the fact that she would like to send a single word memory load for each observation which set both the Enable flag and the Error Flag. This can be accomplished by using word 169 bits 01:15 for the YFGIMPEN flag and word 169 bit 16:16 for YFGIMPER. At the beginning of each observation, the command would be sent to set the enable flag and clear the error flag such that in binary, the memory word load would be:

0000000000000010

A 1 in bit 15 = GIMP corrections enabled for this observation. A 0 in bit 15 = GIMP corrections disabled for this observation. A 0 in bit 16 = no error in FSW computations of this correction, A 1 in bit 16 = an error occurred in the GIMP correction FSW.

The modification to the SHPF file in the PDB would then become:

YPCBTMP Y11T330A16516509:16PHOTOCATHODE B TEMP	HEX	HP 001220
YPCBTMP PHOTOCATHODE B TEMP		TI 001230
YPAMBTMPY11T331A16616609:16PRE-AMP ASSEMBLY B	HEX	HP 001240
YPAMBTMPPre Amp Assy B Temp		TI 001250
YPMFBTMPY11T333A16716709:16PERMANENT MAGNET B	HEX	HP 001260
PMFBTMPPerm Mag B Focus Assy B Temp		TI 001270
XYDFTMPY03T334A16816809:16XY DEFLECTION FOCUS	HEX	HP 001280
XYDFTMPXY Defl Foc DAC Temp		TI 001290
YFGIMPEN 16916901:15GIMP ENABLE FLAG		
YFGIMPENGIMP Enable Flag		
YFGIMPER 16916916:16GIMP ERROR FLAG		
YFGIMPERGIMP Error Flag		
ZSYSON1 Z03X501B26026009:09HRS Sys 1 On Indictr	INT	HP 001300
ZSYSON1		TI 001310
ZMAJFR1 Z01Q503D26026010:12HRS Maj Frame # 1	INT	HP 001320
ZMAJFR1		TI 001330
ZPAGE1 Z01Q505D26026013:16HRS Page # 1	INT	HP 001340
ZPE1		TI 001350

Please let me know if you have any questions. Thanks,

John

From: STSCIC::FSW1::STNGTF512 "Glenn Foley, GSFC/Code 512, (301)285-  
20-DEC-1991 14:40:41.54  
To: SCIVAX::FITCH, SCIVAX::BALZANO, JOHN, STNJRLMOC, MICHELLE, GLENN  
CC:  
Subj: FOS SOI's and TLM Changes for GIMP, Overlite, and Autosafe

John/Vicki/John/Jeff/Michelle/Me -

The following are the proposed 4.0 TLM changes for autosafe removal/GIMP addition and proposed SOI's for new overlite check and GIMP. Please provide comments ASAP. John F.: I'll FAX you preliminary M&B markups by 12/24.

Please note: the SOI for the overlite "final exposure" table has been changed from the "YFNPFLG" originally proposed to "YFFEPFLG" to reflect the difference in usage discussed at the last FSWWG, if that's still OK with Vicki...

Also - I added the GIMP Tick counter to TLM - that still leaves 13 spares in NSSC-I TLM slots.

Thanks,  
Glenn

#### telemetry

changes (FOS ED word 9, subcom 60)

\*\*\*\*\*

mf 8, 68: YFASST (auto safe status) -> spare  
mf 14, 74: spare -> YFXGIMPC (FOS calculated X GIMP Correction)  
mf 15, 75: spare -> YFYGIMPC (FOS calculated Y GIMP Correction)  
mf 18, 78: YSFFLG (auto safe flag) -> spare -> YFGMPTIK (FOS GiMP TIcK counter)  
mf 42, 102: spare -> YFGMPFCE (FOS GiMP FunCtion Enable ["high level enable"])  
mf 47, 107: spare -> YFGMPCRE (FOS GiMP CoRrection Enable ["low level enable"])  
mf 48, 108: spare -> YFGMPERR (FOS GiMP ERRor flag)

note: mf 42 was still defined in the M&B as reporting YMFECT, an item that was deleted from the flight software in 1985. We shall reassign it as part of the CCR.

#### SOI

\*\*\*\*\*

YFGIMPCB - FOS GIMP Coefficient Buffer (hold new coefficient & "zero time")  
(YFGIMPCB is a 9 word buffer)  
YFGMPFCE - FOS GiMP FunCtion Enable ("high level enable" - compute corrections)  
YFGMPCRE - FOS GiMP CoRrection Enable ("low level enable" - issue corrections)  
YFGMPSTA - FOS GiMP STatus (for SHP GIMP information, as described by John F.)  
YFFEPFLG - FOS Final Exposure in this Pointing FLaG (for overlite)

-- fin --

286-5809"

From: FSW1::STNGTF512 "Glenn Foley, GSFC/Code 512, (301)286-5809" 9-JAN-19  
08:52:54.54  
To: HSTFSW, GEIGER, STNJRLMOC, SCIVAX::FITCH, SCIVAX::BALZANO  
CC:  
Subject: Final FOS GIMP PDL Walkthrough

The final walkthrough of 4.0 FOS changes, including GIMP, new overlite, and safing from limit failures will be Friday, Jan 17 from 1 to 4PM in Bldg 3 Room 200. What you see is what you will get.

Jeff, Sam - we'll reschedule the QUEEN meeting.

John F., Vicki, Jeff - let me know if you plan on attending so we can get you a copy of the handout in advance.

- Glenn

From: FSW1::STNJEHCES "John Hueber - (301) 286-2481" 14-JAN-1992 19:08:20.28  
To: SCIVAX::FITCH,STNJEHCES  
CC:  
Subj: PDL for GIMP review

John, following is a difference listing, numbered source listing and a PDL output listing for the review this friday. I thought this would be the best way to get it to you. Let me know if you need anything else.

John

18.23

0.28  
SFOG1::FSWI::STNJEHCES

"John Hueber - (391) 226-444" (391) 226-444

18.23

SCIVAX::BALZANO, STNJEHCES

subj: GIMP, Overlite redesign, etc Design review

Vacki, here's a copy of everything for you. the following mail messages will be differences, numbered source and PDL output listing for the PDL. Let me know if you have any questions or further needs!

John

To: Distribution  
From: John E. Hueber/CES  
Date: January 15, 1992  
Subject: PDL Review for PTRs 1517, 1518 and 1532

The design review for PTRs STP-G 1517 (FOS Geomagnetically Induced Image Motion Problem), 1518 (FOS Change Overlite Error Response), and 1532 (Safe FOS After Two Consecutive Limit Violations) will be on Friday, Jan 17 from 1 to 4PM in Bldg 3 Room 200.

The changes for PTR 1517 (FOS Geomagnetically Induced Image Motion Problem) are as follows:

1. Add a GIMP subroutine which, when enabled, calculates detector deflection corrections (deltas), performs limit checking on the resulting corrections, and when allowed, builds serial magnitude commands including the corrections into FOS Unique Sequence 3, and requests activation of the sequence to send the corrections to the instrument.
2. Add data arrays and variables in the FOS general data area (YFDATA), the FOS software telemetry table (YFEWD9), the Current Value Table in the Standard Header Packet (MECOMCVT), and the Housekeeping Processor data area (put in YFDATA).
3. Add definitions for FOS unique Sequence 3 (YFUNRFGS and MFSCPDTA). The modifications to MFSCPDTA are not included in this review.

The changes for PTR 1518 (FOS Change Overlite Error Response) are as follows:

1. Modify the response to the first overlite error to activate FOS Unique sequence 3 containing a command to close the entrance aperture door.
2. Modify the response to no error following one or more overlite errors to post a status buffer message only if a "new pointing or final exposure in pointing" flag is set.
3. Add a definition for the "new pointing or final exposure in pointing" flag (YFDATA).

The changes for PTR 1532 (Safe FOS After Two Consecutive Limit Violations) are as follows: